


6 DENOTES CRITICAL CHARACTERISTICS.



4 DENOTES A CHARACTERISTIC THAT PROVIDES AN INDICATION OF PROCESS PERFORMANCE. PROCEDURE FOR MEASUREMENT



- NOTES CP DIMENSIONS; -MINIMUM CP VALUE
CAN BE WITHIN THE DIMENSIONAL LIMITATIONS

- BE WITHIN THE DIMENSIONAL LIMITATIONS
ON DRAWING AND INITIALLY LOCATED TO
FOR MAXIMUM TOOL LIFE.

100% MONEY BACK GUARANTEE

1. WIRE LEADS ARE MOLDED INTO FUSEHOLDER BODY.
2. DIMENSIONS IN INCHES, [mm].

[illegible]