



①

②



3



TOOL 5-24-4

— NOTES —

⑤ CHECK ALL PARTS AND SUB-ASSEMBLIES TO DWGS.
AVAILABLE BEFORE ASSY OPERATIONS, SEE
DWG NO'S LISTED ON THIS SHEET.

— OPERATIONS —

FIXTURE*

9242

7146	0	
5012	0	

88525

LET	WAS	DATE	BY	LET	WAS	DATE	BY	MATERIAL	DRAWN	CHECKED	APPR'D	SCALE	USED ON	DATE DRAWN
										✓				2-4-60
								FINISH	COLE-HERSEE COMPANY BOSTON 27, MASS., U.S.A.					DATE ISSUED
								TOLERANCES FRACTIONAL ± DECIMAL ±	NAME ASSEMBLY PROCEDURES					PART NO. 9242